

SUMC TRUSTEE WISH LIST 2009

BRING ELECTRICITY TO THE POND AREA - APPROXIMATE COST \$15,000.00

trench in conduit from the church to North side of parking lot to first light pole
set up a junction box
conduit down pole to wooden walk way
run down to bench area and set a second junction box
continue to the end of walk way and set post
install 100amp 20 circuit waterproof panel
pull all the wires and connect to electrical panel inside of the church
repair black top

REPLACE WINDOWS - APPROXIMATE COST \$3,250.00 - will wait until Spring for quote
Three sets of windows at rear of sanctuary that are by roof top air conditioners
are exposed to secondary water splash and need replacement

DAY CARE - ADD LOCKS TO THE DAY CARE DOORS APPROXIMATE COST \$1,000.00
The day care would like to be able to "lock down" the doors to their rooms
as a precautionary measure

EGRESS WINDOWS - APPROXIMATE COST (?) We will wait until Spring for quotes
The windows in the basement at the front of the church are in very poor condition
and need to be replaced.

PARKING LOT - REPAIR/RESURFACE APPROXIMATE COST (?)
The entire church parking lot is showing its age and will need to be repaired
and/or replaced

s

in